

T +43 3136 500-0 F +43 3136 525-01 sensors@ams.com www.ams.com



Nurnberg, November 15, 2018

Product discontinuation

Dear Customer,

We are sorry to announce that further production of

"XF768_LCC_WB_AR_v1.0 FT SE" (ordering code: 301050003)

cannot be supported any longer.

Reason for that is that the underlying technology is nearing its end and the total demand has declined to such a level that an economic production can no longer be warranted.

Please be informed that the discontinuation of the XF768 sensors will be implemented with immediate effect.

For any further questions (e.g. definition of an EOL agreement) please feel free to contact our customer support team at any time.

Best regards,

Peter Crabbe

ams AG

Director Operations CIS